

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/17/2020

Submitted Date:

12/20/2020

Document Number:

692402781**FIELD INSPECTION FORM**Loc ID 334864 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc.inspections@caerusoil ndgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211085	WELL	SI	04/01/2020	GW	045-06843	KRK 7-8	RI
260667	WELL	PR	06/07/2012	GW	045-07896	KRK 7-2A (H7)	RI
260668	WELL	PR	04/05/2002	GW	045-07897	KRK 7-1A (H7)	RI
260669	WELL	PR	08/26/2002	GW	045-07898	KRK 7-7A (H7)	RI
261362	WELL	PR	06/04/2003	GW	045-07947	KRK 7-8A (H7)	RI

**General Comment:**

This is an Interim Reclamation & Stormwater focused Inspection, a Follow Up to InspDoc#692402646 Dated 10/30/20. Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

Inspected Facilities				
Facility ID: <u>211085</u>	Type: <u>WELL</u>	API Number: <u>045-06843</u>	Status: <u>SI</u>	Insp. Status: <u>RI</u>
Facility ID: <u>260667</u>	Type: <u>WELL</u>	API Number: <u>045-07896</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>260668</u>	Type: <u>WELL</u>	API Number: <u>045-07897</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>260669</u>	Type: <u>WELL</u>	API Number: <u>045-07898</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>261362</u>	Type: <u>WELL</u>	API Number: <u>045-07947</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Date Final Reclamation Started: _____	Date Final Reclamation Completed: _____
Final Land Use: _____	
Reminder: _____	
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____
Debris removed _____	No disturbance /Location never built _____
Access Roads _____	Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____	
Location and associated production facilities reclaimed _____	Locations, facilities, roads, recontoured _____
Compaction alleviation _____	Dust and erosion control _____
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____
1004.d. FINAL VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA%	_____
TRANSECT RESULTS OF REFERENCE AREA%	_____
TOTAL % OF DESIRABLE VEGETATION COVER	_____
VEGETATIVE COVER	_____
Comment:	<div style="border: 1px solid black; height: 20px; width: 100%;"></div>
Corrective Action:	<div style="border: 1px solid black; height: 20px; width: 100%;"></div>
	Date _____

Inspector Name: Colby, Lou

Overall Final Reclamation		Well Release on Active Location		Multi-Well Location		
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<div>Comment: <div>It appears that Stormwater pooling in entry area; leading to rutting, and degradation of pad surface has been resolved; though snow cover prevented through assessment.</div></div> <div>Corrective Action: <div> </div></div> <div>Date: <div> </div></div>						
<b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692402791	Inspection Photos RI	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5314605">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5314605</a>