

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2020

Submitted Date:

12/14/2020

Document Number:

699502024**FIELD INSPECTION FORM**Loc ID 317653 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239697	WELL	PR	03/20/1995	OW	123-07485	SUCKLA-BROWN UNIT NAV 7	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment: Weeds growing around fencing see pic 1

Corrective Action: Comply with 603 f.

Date: 01/14/2021

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type PUMP JACK

Comment: 4' barb wire

Corrective Action:

Date:

Equipment:

corrective date

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment: electric motor

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: Electric

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities

Facility ID: 239697 Type: WELL API Number: 123-07485 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Annual bradenhead test not current. Contact COGCC engineering12/24/2020Corrective Action: Comply with 341 c.

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 12/14/20 at approximately 1300 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Suckla Brown Unit Nav 7</p> <p>Company Name- KPK</p> <p>API- 05-123-07485</p> <p>In Weld County Colorado.</p> <p>While there, I observed producing well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Annual Bradenhead test not current. Contact COGCC engineering</p> <p>Comply with 341 c. 12-24-20</p> <p>Weeds growing around fencing see pic 1</p> <p>Comply with 603 f. 1-14-21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>At time of inspection weather conditions were cold, calm, recent snow.</p> <p>This is a summary of inspection report.</p>	medinaj	12/14/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402554331	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5310445
699502025	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5310440