

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/21/2020

Submitted Date:

12/22/2020

Document Number:

699502047

FIELD INSPECTION FORM

Loc ID 320303 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10369
Name of Operator: NATURAL RESOURCE GROUP INC
Address: 801 WEST MINERAL AVE STE 202
City: LITTLETON State: CO Zip: 80120

Findings:

- 18 Number of Comments
- 9 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Bacon, Duane	303-545-2620/303-579-6353	energyoilandgas@gmail.com	All inspections
Pesicka, Conor		conor.pesicka@state.co.us	
,		dnr_cogccengineering@state.co.us	
Laird, Paul	303-419-6005/303-797-5417	plaird@diversifiedresources.com	All Inspections
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203411	WELL	SI	01/01/2019	GW	001-08920	LEWTON COMPANY F UNIT 1	SI

General Comment:

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	no content label, capacity, or NFPA on concrete buried vault. No capacity, or NFPA on partially buried fiberglass vault. No emergency number on tank battery. No NFPA placard or capacity on separator.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: <u>07/12/2017</u>
Emergency Contact Number:			
Comment:	No emergency contact number on tank battery		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: <u>07/12/2017</u>
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds unmanaged around location		
Corrective Action:	Comply with Rule 603.f .		Date: <u>05/12/2019</u>
Type	OTHER		
Comment:	stained soil under separator see pic 6		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.		Date: <u>07/12/2017</u>
Type	OTHER		
Comment:	Inadequate berms around separator Steel oil tank, fiberglass tank, and buried concrete vault. See pic 1,2,3		
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).		Date: <u>07/12/2017</u>
Type	OTHER		
Comment:	Bradenhead is not plumbed to surface. Bradenhead monitoring has not been performed. Contact COGCC engineering.		
Corrective Action:	Comply with 341 b.		Date: <u>01/01/2021</u>
Type	OTHER		
Comment:	Well has been shut in since 9/1/2017. Mechanical integrity test needs to be performed to ensure mechanical integrity of wellbore. Contact COGCC engineering		
Corrective Action:	Comply with 326 b. (1)		Date: <u>12/22/2020</u>
Type	OTHER		
Comment:	Mechanical issue with separator see pic 6		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: <u>07/12/2017</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Bird Protectors # 1			corrective date
Comment: <input style="width: 100%;" type="text"/>			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:	Bradenhead not plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Automation		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Berms are inadequate			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth						
Comment: Berms inadequate						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1		BV CONCRETE		,	
Comment:						
Corrective Action:				Date:		
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth						
Comment: Berms inadequate						
Corrective Action:				Date:		
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 203411 Type: WELL API Number: 001-08920 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Annual bradenhead test not on record. Bradenhead is not plumbed to surface. According to COGCC data this well has not had a bradenhead test. Contact COGCC engineering

01/01/2021

Corrective Action: Comply with 341 C

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 12/21/2020 at approximately 1300 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Lewton Company F unit 1 Company Name- Natural Resource Group INC API- 05-001-08920 In Adams County Colorado. While there, I observed Shut in well. This is a follow up inspection from document # 685100889 , 688400401 685503179 Corrective Actions are Delinquent. During this inspection the following possible compliance issues were observed: no content label, capacity, or NFPA on concrete buried vault. No capacity, or NFPA on partially buried fiberglass vault. No emergency number on tank battery. No NFPA placard or capacity on separator. Install sign to comply with Rule 210.b. 7/12/2017 No emergency contact number on tank battery Install sign to comply with Rule 210.b. 7/12/2017 Weeds unmanaged around location Comply with Rule 603.f . 5/12/2019 Mechanical issue with separator see pic 6 Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.v7/12/2017 stained soil under separator see pic 6 Properly treat or dispose of oily waste in accordance with 907.e. 7/12/2017 Inadequate berms around Steel oil tank, fiberglass tank, and buried concrete vault. See pic 1,2,3 Repair or install berms or other secondary containment devices per Rule 906.d.(1). 7/12/2017 Well has been shut in since 9/1/2017. Mechanical integrity test needs to be performed to ensure mechanical integrity of wellbore. Contact COGCC engineering Comply with 326 b. (1) 12/22/2020 Bradenhead is not plumbed to surface. Bradenhead monitoring has not been performed. Contact COGCC engineering. Comply with 341 b. 1/1/2021 Annual bradenhead test not on record. Bradenhead is not plumbed to surface. According to COGCC data this well has not had a bradenhead test. Contact COGCC engineering Comply with 341 C 1/1/2021 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. On 4/24/20 I, inspector Justin Medina mistakenly approved this site as in compliance Document # 699501167 At time of inspection weather conditions were sunny, cold, recent snow, muddy location. This is a summary of inspection report.</p>	<p>medinaj</p>	<p>12/22/2020</p>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699502048	Pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5314904