

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2020

Submitted Date:

12/28/2020

Document Number:

699602136**FIELD INSPECTION FORM**Loc ID 337088 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 38 PALMER CREST CTCity: SPRING State: TX Zip: 77381**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	<a href="#">Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282204	WELL	PR	12/22/2005	GW	125-09791	CROSSLAND 32-33 5N46W	PR

**General Comment:**[Follow-up FIR Doc#688000276](#) [Routine Site Inspection FIR](#)

**Location****Lease Road:**

Type	Access		
comment:	Cropland with seasonal access		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	GMR		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Satisfactory		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: No visual impact remaining from Doc#688000276

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	Steel panel		
Corrective Action:		Date:	

**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:	Calibration cert in place		
Corrective Action:		Date:	
Type: Other	# 0		
Comment:	No change in equipment inventoried		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:	None		
Corrective Action:		Date:	

**Flaring:**

Type		
------	--	--

Comment:	None		
Corrective Action:		Date:	

<b>Inspected Facilities</b>				
Facility ID: 282204	Type: WELL	API Number: 125-09791	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	GW			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Cropland with annual tillage](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699602237	GMR-Wellhead-Fencing-PJ-PM	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5316757">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5316757</a>