

**Inspection Photos**  
**Operator: Enduring Resources**  
**API: 067-07758**  
**Date: 12/22/2020**



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of Russian olive trees along the western edge of the project area.



Photo 3. View of revegetation within the western project area.



Photo 4. View of cobble along roadside drainage full of sediment. BMP is not adequate here.



Photo 5. View of reference area comprised of pinyon and juniper woodland with understory of mountain mahogany, gambel oak, and antelope bitterbrush.