

Inspection Photos

Operator: Enduring Resources
API: 067-08771
Date: 12/22/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of Russian thistle debris within the northeastern corner of the project area.



Photo 3. View of the southern project area from the southwestern corner facing eastward. Vegetation outside of the fenced working area is established. This slope is bermed and appears stabilized.



Photo 4. View of the western project area from the southwestern corner facing northward.



Photo 5. View of reference area comprised of pinyon and juniper woodland with understory of mountain mahogany, gambel oak, and antelope bitterbrush.