

Inspection Photos
Operator: Enduring Resources
API: 067-07769
Date: 12/22/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward.



Photo 3. View of the eastern project area from the southeastern corner facing northward. Revegetation is comprised of western wheatgrass, smooth brome, and sand dropseed.



Photo 4. View of reference area comprised of pinyon and juniper woodland with understory of mountain mahogany, gambel oak, and antelope bitterbrush. Grasses and forbs such as Indian ricegrass, sand dropseed, and penstemon are present.