

Inspection Photos
Operator: Enduring Resources
API: 067-08398
Date: 12/22/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Vegetation is sparse, weeds appear to be grazed.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of reference area comprised of open grass field, largely snow covered at this time.