

# Inspection Photos

Operator: Enduring Resources  
API: 067-07468  
Date: 12/22/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Vegetation is sparse. Evidence of mulching and installation of BMPs observable, although a thorough stormwater and vegetation assessment was not conducted due to snow cover.





Photo 3. View of the eastern project area from the southeastern corner facing northward. Dense Russian thistle debris observed along the fenceline.



Photo 4. View of reference area comprised of pinyon and juniper woodland with gambel oak, mountain mahogany, antelope bitterbrush and grasses and forbs such as sand dropseed, Indian ricegrass, and prickly pear.





Photo 5. View of closed gate after leaving location