



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Prime Mover

# 1

Comment: Electric motor

Corrective Action:

Date:

Type: Pump Jack

# 1

Comment:

Corrective Action:

Date:

Type: Bradenhead

# 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: Electric

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 240594 Type: WELL API Number: 123-08382 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error  
 Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: \_\_\_\_\_  
 Comment: Annual bradenhead test is not current. COn tact COGCC engineering. 01/01/2021  
 Corrective Action: Comply with 341 c. Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On 12/22/2020 at approximately 1020 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- Paul Heinze 1                      Company Name- KPK                      API- 05-123-318092                      In Weld County Colorado.                      While there, I observed Well Type                      During this inspection the following possible compliance issues were observed:                      Annual bradenhead test is not current. Contact COGCC engineering.                      Comply with 341 c. 1/1/2021                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      At time of inspection weather conditions were Sunny, cold, recent snow.                      This is a summary of inspection report.</p>	medinaj	12/22/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402559040	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5314918">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5314918</a>
699502056	Pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5314908">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5314908</a>