

Inspection Photos
Operator: Enduring Resources
API: 067-07759
Date: 12/22/2020



Photo 1. View of the project area from the well pad entrance facing center.




Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Approximately 200 Russian knapweeds observed on the fill slope (shown in inset). Infestation is not being controlled. Russian thistle debris along the fenceline.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with gambel oak, antelope bitterbrush, Indian ricegrass, and mountain mahogany.