

Inspection Photos

11/24/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 312672

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312672



Photo 1: Figure attached to SOVR #402525408 provided by Caerus; Photo shows access road (green) not to be reclaimed, and the well Location (Blue) that remains subject to COGCC 1000 series requirements. Access road requires graveling per COAs.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312672



Photo 2: Photo taken from the access road entrance north of the Location, facing south. Per doc. #402525408, 1004 reclamation requirements of the access road has been waived; access road requires gravelling.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312672



Photo 3: Continued from photo 2. Access road requires graveling. BMPs installed on/along access road need to be installed in accordance with good engineering practices pursuant to 1002.f Rules.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312672



Photo 4: Photo taken from the access road, facing south. Photo shows sediment trap along access road. BMP has not been installed in accordance with good engineering practices.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312672



Photo 5: Continued from photo 4. Photo shows outlet at sediment trap has not been constructed in accordance with good engineering practices.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312672



Photo 6: Photo taken from the fenced Location's entrance. Per figures provided by the Operator, these areas will be reclaimed.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312672



Photo 7: Photo taken from the northwest end of the Location, facing east. Photos 7-9 provide an overview of the Location from east, southeast to south.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312672



Photo 8: See comments under photo 7.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312672



Photo 9: See comments under photo 7.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312672




Photo 10: Photo taken from the Location, facing east. Photo shows vehicle travel on the location has resulted in deep ruts throughout the reclamation area; Additional reclamation work will be required in these areas to repair rutting, address potential compaction and revegetation concerns resulting from vehicle use.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312672



Photo 11: Photo taken from the Location. Photo shows additional seeding/stabilization activities appear to have recently been conducted.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312672



Photo 12: Photo taken from the east end of the Location, facing southeast. Photo shows example of perimeter BMPs that have not been installed in accordance with good engineering practices.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312672



Photo 13: Continued from photo 12. Photo shows perimeter BMPs have not been installed in accordance with good engineering practices.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312672



Photo 14: Photo taken from the southern area of the Location, facing east. Photo shows vehicle travel on the location has resulted in deep ruts throughout the reclamation area; Additional reclamation work will be required in these areas to repair rutting, address potential compaction and revegetation concerns resulting from vehicle use.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312672



Photo 15: Photo taken from the northwest end of the Location, facing west. Photo shows Access road at location entrance was constructed in a manner that dammed a drainage on the west end of the Location; BMPs missing or insufficient to allow water movement within the drainage. Access road requires graveling



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312672




Photo 16: Continued from photo 15. Photo shows Access road at location entrance was constructed in a manner that dammed a drainage on the west end of the Location; BMPs missing or insufficient to allow water movement within the drainage. Access road requires graveling. Photo also example of BMPs missing, or insufficient to stabilize slopes of the Location.