



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Pump Jack	# 1				
		Comment:			
		Corrective Action:		Date:	
Ancillary equipment	# 1				
		Comment: <a href="#">Electric / automation</a>			
		Corrective Action:		Date:	
Gas Meter Run	# 1				
		Comment: <a href="#">Calibrated 12/17/20</a>			
		Corrective Action:		Date:	
Prime Mover	# 1				
		Comment: <a href="#">electric motor</a>			
		Corrective Action:		Date:	
Bradenhead	# 1				
		Comment:			
		Corrective Action:		Date:	
Horizontal Heated Separator	# 1				
		Comment:			
		Corrective Action:		Date:	
Bird Protectors	# 1				
		Comment:			
		Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	100 BBLs	PBV FIBERGLASS		,
		Comment: <a href="#">One tank 50 BBL</a>			
		Corrective Action:		Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: shares containment with oil tank				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					
Date:					

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
Date:		

**Flaring:**

Type	
Comment:	
Corrective Action:	
Date:	

**Inspected Facilities**

Facility ID: 202953 Type: WELL API Number: 001-08358 Status: PR Insp. Status: PR

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: \_\_\_\_\_

Comment: Annual Bradenhead test is not current. Contact COGCC engineering.

01/07/2021

Corrective Action: Comply with 341 c

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On 12/28/20 at approximately 1300 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- Guthrie 2                      Company Name- KPK                      API- 05-001-08358                      In Adams County Colorado.                      While there, I observed Producing well                      During this inspection the following possible compliance issues were observed:                      Annual bradenhead test is not current. Contact COGCC engineering.                      Comply with 341 c 1/7/21                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	medinaj	12/28/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699502062	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5317790">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5317790</a>