

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/28/2020

Submitted Date:

12/28/2020

Document Number:

699502059**FIELD INSPECTION FORM**Loc ID 327177 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10662Name of Operator: NANKE ENERGY LLCAddress: 2440 RANCH RESERVE RDGCity: WESTMINSTER State: CO Zip: 80234**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Nanke, Kevin	(303) 618-4507	knanke@lilisenergy.com	
		knanke@knconsultinginc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246475	WELL	SI	06/01/2018	OW	123-14272	SAWYER 32-2	SI

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 246475 Type: WELL API Number: 123-14272 Status: SI Insp. Status: SI

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Workover**

Comment:  This well is set to have a mechanical integrity test performed.  
At time of inspection workover rig crew was in process of rigging up.  
After rigging up pulling unit rig crew was in process of taking off horses head on pump  
jack, and unseating sucker rod pump. Well has been shut in since 6/1/2018. Annual  
bradenhead test is current.

Corrective Action:

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
At time of inspection weather conditions were snowing, cold, slight wind. Work being performed on this site is to bring Shut in status of well into compliance with COGCC rules via mechanical integrity test.	medinaj	12/28/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699502060	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5317789">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5317789</a>