

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/29/2020

Submitted Date:

12/29/2020

Document Number:

700702080

**FIELD INSPECTION FORM**

Loc ID 316146 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 200502  
Name of Operator: 31 OPERATING  
Address: 3021 RIDGE RD #156  
City: ROCKWALL State: TX Zip: 75032

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
operating, 31		kfreeman@31operating.com	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232238	WELL	PR	09/25/2003	GW	103-09909	ANT HILL UNIT 30-31	SI

**General Comment:**

COGCC Inspection Report Summary

On 12/23/20, I, Inspector Scott Ramsey, conducted a Safety and compliance inspection at 31 Operating 30-31, at Location # 316146 in Rio Blanco county Colorado.

This is a limited inspection for Safety and Compliance.

While there, I observed that location has not been visited in quite some time, nor had the access roads been plowed.

During this inspection the following possible compliance issues were observed:

- Debris throughout location (dead weeds)

Refer to photograph of observed compliance issue.

I spoke with Leven who has worked for 31 operations at the lay down yard. He stated that the compressors were pulled out of his field back in October and that he and other pumpers on his side of the field went through and shut all of the wells in November. He had also given me a map of the field and pointed out that he was not sure of some locations that had supply gas running to the burners had been shut off. He also stated that they did NOT evacuate any of the flow lines of fluid. He did not go out to the field with me, he suggested that I could shut the supply gas off if I came across any that needed it. He also stated that all of their phone numbers had been disconnected. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Snow covered/not plowed		
Corrective Action		Date:	

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	• Debris throughout location (dead weeds)		
Corrective Action:	Remove All debris	Date:	02/02/2021

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

<b>Paint</b>	
Condition	Adequate

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 232238 Type: WELL API Number: 103-09909 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702115	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5317876">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5317876</a>