

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/29/2020

Submitted Date:

12/29/2020

Document Number:

700702087**FIELD INSPECTION FORM**Loc ID 316262 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 200502Name of Operator: 31 OPERATINGAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
operating, 31		kfreeman@31operating.com	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259876	WELL	PR	09/20/2005	GW	103-10123	WRD COUNTY 25-11	SI

General Comment:**COGCC Inspection Report Summary**

On 12/23/20, I, Inspector Scott Ramsey, conducted a Safety and compliance inspection at 31 Operating 25-11, at Location # 316262 in Rio Blanco county Colorado.

This is a limited inspection for Safety and Compliance.

While there, I observed that location has not been visited in quite some time, nor had the access roads been plowed.

During this inspection the following possible compliance issues were observed:

- Debris throughout location (dead weeds)

Refer to photograph of observed compliance issue.

I spoke with Leven who has worked for 31 operations at the lay down yard. He stated that the compressors were pulled out of his field back in October and that he and other pumpers on his side of the field went through and shut all of the wells in November. He had also given me a map of the field and pointed out that he was not sure of some locations that had supply gas running to the burners had been shut off. He also stated that they did NOT evacuate any of the flow lines of fluid. He did not go out to the field with me, he suggested that I could shut the supply gas off if I came across any that needed it. He also stated that all of their phone numbers had been disconnected. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:	Snow covered/not plowed		
Corrective Action		Date:	

Overall Good: ☐

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	• Debris throughout location (dead weeds)		
Corrective Action:	Remove All debris	Date:	02/02/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	259876	Type:	WELL	API Number:	103-10123	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: Well is shut in at time of inspection									
Corrective Action: _____ Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Limited storm water inspection due to snow cover](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702122	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5317883