

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/22/2020

Submitted Date:

12/29/2020

Document Number:

699802310

FIELD INSPECTION FORM

Loc ID 316137 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 200502
Name of Operator: 31 OPERATING
Address: 3021 RIDGE RD #156
City: ROCKWALL State: TX Zip: 75032

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Freeman, Kris	254-727-0435	kfreeman@31operating.com	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232223	WELL	PR	12/01/2010	GW	103-09894	WRD DOW 20-22	SI

General Comment:

[COGCC Inspection Report Summary](#)
On Tuesday 12/22/20 I, Inspector Corey De Paolo, Conducted, a safety and compliance Inspection at 31 OPERATING WRD DOW-62N96W /20SENW, Location #316137 in Rio Blanco County Colorado. This is a summary of inspection report.

Location

Lease Road:

Type	Access		
comment:			
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Ancillary equipment	# 1	Chemical tank half full			
Bird Protectors	# 2				
Gas Meter Run	# 1				
Horizontal Heated Separator	# 1				
Plunger Lift	# 1				

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		,
Comment:					

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth					
Comment: Both tanks are full					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 232223 Type: WELL API Number: 103-09894 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Culverts				
Ditches						

Comment: Location covered with snow at the time of inspection.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699802311	Photos for Insp. #699802310	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5318037