

Inspection Photos
Operator: Simcoe
API: 067-07418
Date: 12/23/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Location is largely snow covered. Vegetation is in a grazed condition.



Photo 3. View of the eastern project area from the northeastern corner facing southward. Final reclamation will require revegetation with vegetation representative of the reference area.



Photo 4. View of reference area comprised of pinyon and juniper woodland with understory of sagebrush, sand dropseed, blue grama, and James galleta.