

Inspection Photos
Operator: Enduring
API: 067-08845
Date: 12/23/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Location is largely snow covered. Perennial vegetation is comprised of intermediate wheatgrass.



Photo 3. View of the western project area from the southwestern corner facing northward. Final reclamation will require revegetation with vegetation representative of the reference area.



Photo 4. View of reference area comprised of pinyon and juniper woodland with understory of sagebrush, sand dropseed, blue grama, and James galleta.



Photo 5. View of closed gate after leaving location