

Inspection Photos  
Operator: Simcoe  
API: 067-08877  
Date: 12/23/2020



Photo 1. View of the project area from the western corner facing center.



Photo 2. View of the northern project area from the western corner facing northeastward. Location is largely snow covered. Perennial vegetation is comprised of intermediate wheatgrass and crested wheatgrass. Final reclamation will need to be comprised of native vegetation representative of the reference area.



Photo 3. View of unused equipment parked within the northern project area.



Photo 4. View of Scotch thistles along the access road. Approximately 100 individuals observed.



Photo 5. View of reference area comprised of pinyon and juniper woodland with understory of sagebrush, sand dropseed, blue grama, and James galleta.



Photo 6. View of closed gate after leaving location