

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/16/2020

Submitted Date:

12/28/2020

Document Number:

692402780**FIELD INSPECTION FORM**Loc ID 334967 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc.inspections@caerusoila ndgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271628	WELL	PR	08/27/2004	GW	045-09917	BENZEL 36-15D (N36NWB)	RI
271629	WELL	PR	09/13/2004	GW	045-09918	BENZEL 36-11D (N36NWB)	RI
271630	WELL	PR	10/01/2004	GW	045-09919	BENZEL 36-14D (N36NWB)	RI
271631	WELL	PR	08/23/2004	GW	045-09920	BENZEL 1-5D (N36NWB)	RI
272295	WELL	PR	09/09/2004	GW	045-10057	BENZEL 36-11A (N36NWB)	RI
272297	WELL	PR	08/31/2004	GW	045-10058	BENZEL 36-12D (N36NWB)	RI

General Comment:

This is an Interim Reclamation & Stormwater focused Inspection, a Follow up to Insp Doc#692402651 Dated 10/30/20. Any Corrective Actions from other previous Inspections that have not been addressed are still applicable.

Inspected Facilities				
Facility ID: <u>271628</u>	Type: <u>WELL</u>	API Number: <u>045-09917</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>271629</u>	Type: <u>WELL</u>	API Number: <u>045-09918</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>271630</u>	Type: <u>WELL</u>	API Number: <u>045-09919</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>271631</u>	Type: <u>WELL</u>	API Number: <u>045-09920</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>272295</u>	Type: <u>WELL</u>	API Number: <u>045-10057</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>272297</u>	Type: <u>WELL</u>	API Number: <u>045-10058</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

Date Final Reclamation Started: _____	Date Final Reclamation Completed: _____
Final Land Use: _____	
Reminder: _____	
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____
Debris removed _____	No disturbance /Location never built _____
Access Roads _____	Regraded _____
_____	Contoured _____
Gravel removed _____	Culverts removed _____
Location and associated production facilities reclaimed _____	Locations, facilities, roads, recontoured _____
Compaction alleviation _____	Dust and erosion control _____
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____
1004.d. FINAL VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	Date _____

Inspector Name: Colby, Lou

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [It appears BMPs have been maintained/repared since previous RI Insp, though snow cover restricted definitive assessment. FIRR has been submitted in response to CA, reporting resolution of the Stormwater CA.](#)

Corrective Action: _____ Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692402800	Inspection Photos RI	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5318978