

Inspection Photos

ID:429852

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 12/29/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID: 429852 | Date: 12/29/2020

Inspection Photos



Photo 9. Facing southwest toward the location which is adjacent to County Rd. 44. The facility is not maintained and there are numerous issues observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 429852 | Date: 12/29/2020

Inspection Photos



Photo 2. There is oil stained soil near the Produced Water tank. The tank is labeled produced water but appeared to contain oil inside. Netting was over the top of tank. Additionally the berm does not appear to be sufficient to contain a spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 429852 | Date: 12/29/2020

Inspection Photos



Photo 3. There is a barrel tipped over which is not sealed .



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 429852 | Date: 12/29/2020

Inspection Photos



Photo 4. There are numerous buckets with faded labeling stored with no containment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 429852 | Date: 12/29/2020

Inspection Photos



Photo 5. There is oil stained soil from spills that have occurred. There are several containers that are not labeled and appear to contain oil.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 429852 | Date: 12/29/2020

Inspection Photos



Photo 6. There is oily waste inside this containment which is near the top of the containment and appears to have spilled over.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 429852 | Date: 12/29/2020

Inspection Photos



Photo 7. Facing toward the southwest side. The berm around the tank vessel is inadequate in size and has animal burrows in it.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 429852 | Date: 12/29/2020

Inspection Photos



Photo 8. The facility sign is posted but contains incomplete and inaccurate information.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 429852 | Date: 12/29/2020

Inspection Photos



Photo 9. On the backside of the metal panels is unused equipment. There is various supplies and waste stored in the tanks.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 429852 | Date: 12/29/2020

Inspection Photos



Photo 10. Facing northwest toward the location. The perimeter of the location consists of tall weeds (Kochia) debris which is a fire hazard. The weeds around the perimeter of the location need to be cut and removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 429852 | Date: 12/29/2020