

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/29/2020

Submitted Date:

12/30/2020

Document Number:

690200980

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10626  
 Name of Operator: DOVER ATWOOD CORPORATION  
 Address: 1875 HARSH AVENUE SE  
 City: MASSILLON State: OH Zip: 44646

**Findings:**

- 7 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Kosola, Jason		jason.kosola@state.co.us	
LEVENGOD JOHN		jlevengood07@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429852	GAS COMPRESSOR STATION	AC			-	Walsh/Bishop Gas Compressor	AC

**General Comment:**

[This is a location inspection.](#)  
[See attached photos and additional details within this report.](#)

<b>Location</b>			
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	The QTR QTR and section is not accurate on the sign. Sign not posted or information inaccurate at well(s) or battery.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: <u>03/01/2021</u>
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	The perimeter of the location consists of tall weeds (Kochia) debris which is a fire hazard. The weeds around the perimeter of the location need to be cut and removed.		
Corrective Action:	Comply with Rule 603.f .		Date: <u>01/14/2021</u>
Type	STORAGE OF SUPL		
Comment:	There is unused tanks and supplies stored at the backside of the metal panel wall. Unused supplies and equipment must be removed.		
Corrective Action:	Comply with Rule 603.f .		Date: <u>01/14/2021</u>
Type	STORAGE OF SUPL		
Comment:	There are numerous containers and supplies that are laying on the ground with no containment and do not appear to be in use. Unused supplies and equipment must be removed.		
Corrective Action:	Comply with Rule 603.f .		Date: <u>01/14/2021</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Lube Oil			
Comment:	There is oil stained soil near the black containers which appear to be lube oil (Photo 5). There is also oil in the containment of the white tank which appears to have spilled over on the ground (Photo 6).		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff. Require appropriate cleanup.		Date: <u>12/31/2020</u>
Crude Oil	Tank		
Comment:	There is oil stained soil near the produced water tank.		
Corrective Action:	"Properly dispose of oily waste in accordance with Rule 907.e and contact area COGCC EPS"		Date: <u>01/20/2021</u>
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Venting:</b>			
Yes/No			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690200981	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5319024">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5319024</a>