

Inspection Photos

API: 009-06322

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 12/29/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06322 | Date: 12/29/2020

Inspection Photos



Photo 1. Facing west toward the location. There is equipment that remains and the location has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06322 | Date: 12/29/2020

Inspection Photos



Photo 2. There is a sign, tank, and pipe riser that remains. The well was plugged and abandoned on 9/1/2017. All equipment should have been removed within 3 months of abandonment.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06322 | Date: 12/29/2020

Inspection Photos



Photo 3. Facing southwest. This area has no vegetation growth and has not been regraded and leveled. Soils need to be decompacted by cross ripping to 18 inches.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06322 | Date: 12/29/2020

Inspection Photos



Photo 4. There is an eclectic utility and various parts that remain. All equipment should have been removed within 3 months of abandonment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06322 | Date: 12/29/2020

Inspection Photos



Photo 5. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06322 | Date: 12/29/2020

Inspection Photos



Photo 6. There is cement that remains at the east side. The cement needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06322 | Date: 12/29/2020