

Inspection Photos

API: 009-06554

Operator: LORENTZ OIL & GAS LLC

Inspection Date: 12/29/2020



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06554 | Date: 12/29/2020

Inspection Photos



Photo 1. Facing south toward the access road. Vegetation is well established along the former road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06554 | Date: 12/29/2020

Inspection Photos




Photo 2. Facing west toward the location. There is no vegetation growth at the location. It does not appear reclamation has been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06554 | Date: 12/29/2020

Inspection Photos



Photo 3. View of ground cover shows no vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06554 | Date: 12/29/2020

Inspection Photos



Photo 4. Facing east toward the location. There is no vegetation growth at the location. It does not appear reclamation has been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06554 | Date: 12/29/2020

Inspection Photos



Photo 5. Facing east toward the surrounding undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06554 | Date: 12/29/2020