

Inspection Photos

API: 009-06553

Operator: LORENTZ OIL & GAS LLC

Inspection Date: 12/29/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06553 | Date: 12/29/2020

Inspection Photos



Photo 1. Facing southeast toward the access road. Desirable vegetation has not established along the road. It does not appear reclamation was performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06553 | Date: 12/29/2020

Inspection Photos



Photo 2. Facing north toward the location. There is no vegetation growth at the location. It does not appear reclamation has been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06553 | Date: 12/29/2020

Inspection Photos



Photo 3. View of ground cover shows no vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06553 | Date: 12/29/2020

Inspection Photos




Photo 4. Facing south toward the location. There is no vegetation growth at the location. It does not appear reclamation has been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06553 | Date: 12/29/2020

Inspection Photos



Photo 5. Facing east toward the surrounding undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06553 | Date: 12/29/2020