

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402564502

Date Received:

12/31/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

cogcc@kpk.com

Knop, Max

mknop@kpk.com

Schlagenhauf, Mark

mark.schlagenhauf@state.co.us

Oakman, Kari

kari.oakman@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 690102117

Inspection Date: 10/15/2020

FIR Submit Date: 10/16/2020

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____

Qtrqtr: SESW Sec: 34 Twp: 1N Range: 67W Meridian: 6

Latitude: 40.001946 Longitude: -104.876365

FACILITY - API Number: 05-123-00 Facility ID: 465402

Facility Name: John Weigandt Consolidation Number: _____

Qtrqtr: SESW Sec: 34 Twp: 1N Range: 67W Meridian: 6

Latitude: 40.001946 Longitude: -104.876365

CORRECTIVE ACTIONS:

1 CA# 142760

Corrective Action:

Date: 11/18/2020

Update CA section of supplemental form 19 spill report to include information pertaining to compliance of COGCC series 1100 flowline regulations:
1) Root cause of failure (final determination); measures taken to prevent a recurrence
2) Description of flowline repair, replacement and abandonment work completed (at spill ID #465402; supporting compliance of rule 1102.j. Repair)
3) Contact COGCC Inspector with schedule of post repair pressure testing. Perform OLF flowline pressure testing to verify integrity of repairs/ reconnections completed prior to returning the John Weigandt consolidation flowline to service (rule 1102.j.4 and 1102.O). Upload pressure testing chart to COGCC Form 19 subsequent.
4) Complete abandonment of the historical/ out of service 1" CS flowline per COGCC rule 1105 (ends sealed per 1105.e.4).

Response: CA COMPLETED

Date of Completion: 10/19/2020

Operator Comment: 1) Root cause of the flowline failure was determined to be internal corrosion. 1200 foot section of 4-inch carbon steel flowline replaced with 3-inch HDPE flowline to prevent future corrosion issues.
2) 1200 foot section of 4-inch carbon steel flowline replaced with 3-inch HDPE flowline. Cut ends of HDPE flowline re-connected using carbon steel to HDPE transitions.
3) Off location flowline pressure test completed on October 19, 2020.
4) Ends of out of service 1" flowline have been capped.

COGCC Decision:

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Max Knop

Signed:

Title: Gen Manr of Air Quality

Date: 12/31/2020 1:16:24 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402564517	OLF Pressure Test
-----------	-------------------

Total Attach: 1 Files