

# Inspection Photos

API: 009-06014

Operator: JONES ENERGY LTD

Inspection Date: 12/29/2020




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06014 | Date: 12/29/2020

## Inspection Photos



**Photo 1.** Facing southwest at the beginning of the access road. Desirable vegetation has not established along the road. It does not appear reseeding was performed.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06014 | Date: 12/29/2020

## Inspection Photos



**Photo 2.** Facing southwest along the access road. The greyish vegetative debris is remains of undesirable weeds (Kochia). Desirable vegetation has not established along the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06014 | Date: 12/29/2020

## Inspection Photos



**Photo 3.** Facing southwest toward the location. The location is bare of vegetation. Does not appear any work was performed since the previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06014 | Date: 12/29/2020

## Inspection Photos



**Photo 4.** Facing northeast toward the location. The location is bare of vegetation. Does not appear any work was performed since the previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06014 | Date: 12/29/2020

## Inspection Photos



**Photo 5.** Facing west toward the surrounding undisturbed reference area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06014 | Date: 12/29/2020