

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/22/2020

Submitted Date:

12/31/2020

Document Number:

700404740

**FIELD INSPECTION FORM**

Loc ID 316346 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10654  
Name of Operator: LASSO OIL & GAS LLC  
Address: 3021 RIDGE RD #156  
City: ROCKWALL State: TX Zip: 75032

**Findings:**

- 7 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Freeman, Kris	254-727-0435	kfreeman@31operating.com	
Katz, Aaron		aaron.katz@state.co.us	
Burger, Craig		craig.burger@state.co.us	
Ikenouye, Teri		teri.ikenouye@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268151	WELL	SI	04/01/2020	GW	103-10321	FEDERAL 12-18	PR

**General Comment:**

A follow up inspection of FIR document 700403870.

The following compliance issues were resolved:

- 1) The blow down tank was replaced.

Additional compliance issues:

- 1) Report past due monthly operations on Form 7. Complete by 7-15-2020.
- 2) Provide bradenhead access. Photo 3. Complete by 2-1-2021.
- 3) Calibrate gas meter. Photo 6. Complete by 2-1-2021.
- 4) Gas leaking out of ground at well head. Photos 1, 2, 3. Complete by 2-1-2021.

This is a summary of inspection report 700404740.

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency phone, 800-209-9762, was called on 12-18-2020 @ 16:24, 16:57, 17:19, 20:00, 12-21-2020 @ 11:11, 12-22-2020 @ 18:12, 12-23-2020 @ 17:01, 12-28-2020 @ 20:05. No one answered and no message service was available. Number was answered on 12-31-2020 @ 8:24.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Type: Bradenhead	# 1	Comment: Bradenhead access is not present.	Corrective Action: Provide bradenhead access with appropriate fittings to allow determination of pressure and fluid flow.	Date: 02/01/2021	
Type: Bird Protectors	# 1	Comment:	Corrective Action:	Date:	
Type: Gas Meter Run	# 1	Comment: Meter card has no calibration date.	Corrective Action: Meters need calibrated annually.	Date: 02/01/2021	
Type: Horizontal Heated Separator	# 1	Comment:	Corrective Action:	Date:	
Type: Plunger Lift	# 1	Comment:	Corrective Action:	Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		,

Comment:		
Corrective Action:		Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	5 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 268151 Type: WELL API Number: 103-10321 Status: SI Insp. Status: PR

**Producing Well**

Comment: Last reported monthly operations were for May 2020. Report past due monthly operations. Last recorded production March 2020.  
 No audible gas flow at well or meter building. Values from well head tubing to meter building appeared to be open. Tubing pressure 0 psi. No casing gage present. Digital meter shows "Flow Today 0.3952377".

Corrective Action: **Submit required Form 7(s) to COGCC.**

Date: 07/15/2020

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: [Snow on ground.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

