

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/28/2020

Submitted Date:

01/03/2021

Document Number:

688309250

### FIELD INSPECTION FORM

Loc ID 322171 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10395  
Name of Operator: GOODWIN ENERGY MANAGEMENT LLC  
Address: 740 S OGDEN STREET  
City: DENVER State: CO Zip: 80209

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Goodwin, Scott	(303) 478-4800	scottgoodwinjr@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209477	WELL	PR	04/01/2020	OW	039-06382	HOERY 24-02	PR

**General Comment:**

Reinspection, passed, Form 7s are up to date



Comment:	gas engine	Date:	
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:		Date:	
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	same earth berms as crude oil tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above**

API Number
039-06382

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No		
--------	--	--

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Location Construction**

Location ID: 209477      CDP: \_\_\_\_\_

Comment:

Corrective Action:       **Date:** \_\_\_\_\_

**Form 2A COAs:**

**Comment:**

Corrective Action:       **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:**

Corrective Action:       **Date:** \_\_\_\_\_

**Comment:**

**Corrective Action:**       **Date:** \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_      Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_      Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_      Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_      Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_      Phone Number: \_\_\_\_\_      Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: 209477 Type: WELL API Number: 039-06382 Status: PR Insp. Status: PR

**Producing Well**

Comment: [PR. 10/1/2020 production reported to COGCC database. No gas produced.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688309342	Goodwin Energy Management LLC, Hoery 24-02	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5320397">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5320397</a>