

# Inspection Photos

API: 009-05050

Operator: COLORADO INTERSTATE GAS  
COMPANY LLC

Inspection Date: 12/29/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05050 | Date: 12/29/2020

## Inspection Photos



**Photo 1.** Facing southwest along the access road near the location. This area of the road has not been recontoured.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05050 | Date: 12/29/2020

## Inspection Photos



**Photo 2.** Facing southwest toward the location. The location has not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05050 | Date: 12/29/2020

## Inspection Photos



**Photo 3.** Facing south at the location. There are areas of the location that have no vegetation growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05050 | Date: 12/29/2020

## Inspection Photos



**Photo 4.** There is a pipe riser that remains at the west side of the location. All equipment should have been removed within 3 months of abandonment of the well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05050 | Date: 12/29/2020

## Inspection Photos



**Photo 5.** There is another pipe riser that remains at the center of the location. All equipment should have been removed within 3 months of abandonment of the well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05050 | Date: 12/29/2020

## Inspection Photos



**Photo 6.** Facing northwest toward the location. The location has not been reclaimed and is bare of vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05050 | Date: 12/29/2020