

Inspection Photos

API: 009-06099

Operator: SOVEREIGN OPERATING COMPANY

Inspection Date: 12/29/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06099 | Date: 12/29/2020

Inspection Photos



Photo 1. Facing east toward the access road. The road is recontoured and reclaimed. Vegetation has re-established along the former road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06099 | Date: 12/29/2020

Inspection Photos



Photo 2. Facing east toward the location. Desirable vegetation has re-established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06099 | Date: 12/29/2020

Inspection Photos



Photo 3. Facing west toward the location. Desirable vegetation has re-established at the location. There are some undesirable weeds (Kochia) however, underneath the weeds are desirable vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06099 | Date: 12/29/2020

Inspection Photos



Photo 4. View of groundcover at the location shows desirable vegetation consisting of Sand dropseed, Blue grama, Western wheat grass, among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06099 | Date: 12/29/2020

Inspection Photos




Photo 5. Facing south toward the surrounding undisturbed area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06099 | Date: 12/29/2020