

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/28/2020

Submitted Date:

01/04/2021

Document Number:

700404828

**FIELD INSPECTION FORM**

Loc ID 314716 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10654  
Name of Operator: LASSO OIL & GAS LLC  
Address: 3021 RIDGE RD #156  
City: ROCKWALL State: TX Zip: 75032

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	
Ikenouye, Teri		teri.ikenouye@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Freeman, Kris	254-727-0435	kfreeman@31operating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229394	WELL	SI	12/01/2019	OW	103-07049	GEBAUER 14	SI

**General Comment:**

A routine inspection identified the following compliance issues:  
 1) Report past due monthly operations on Form 7. Complete by 7-15-2020.  
 2) Gas coming out of casing open to the atmosphere. Contact COGCC engineering. Photos 2 & 3.

This is a summary of inspection report 700404828.

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:	Tank sounded empty.				
Corrective Action:				Date:	

**Paint**

Condition

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No			
Comment:	Casing gas coming out of 2 holes in top plate of well. See FLIR video.		
Corrective Action:	Contact the COGCC Area Engineer for next steps.		
		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 229394 Type: WELL API Number: 103-07049 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last reported monthly operations were for May 2020. Report past due monthly operations. Last recorded production November 2019.  
No audible flow at well. Pump jack idle at time of inspection. Power is on at power panel. No pressure gages present.

Corrective Action: **Submit required Form 7(s) to COGCC.** Date: 07/15/2020

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: [Snow on ground.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

