

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/04/2021

Submitted Date:

01/04/2021

Document Number:

699502107

FIELD INSPECTION FORM

Loc ID 319896 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #225
City: AURORA State: CO Zip: 80016

Findings:

- 7 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
Espinosa, Bill		billespinosa30@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201803	WELL	SI	06/01/2018	OW	001-07207	CHAMPLIN 78 AMOCO B 1	SI

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds uncontrolled on location see pic 1,3,4,5,6,7		
Corrective Action:	Comply with 603 f	Date:	01/14/2021
Type	OTHER		
Comment:	Well has been shut in since 6/1/2018 and needs a mechanical integrity test to ensure wellbore integrity. Contact COGCC engineering		
Corrective Action:	No current MIT on record or delinquent as required by Rule 326	Date:	01/04/2021
Type	OTHER		
Comment:	no BMP under chemical tanks see pic 4,5,6,7		
Corrective Action:	Install adequate BMB for storage of materials that could result in the discharges causing pollution of surface waters per rule 1002 f (2)B	Date:	01/14/2021
Type	OTHER		
Comment:	stained soil around pump jack see pic 3,4,5,6,7		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	02/04/2021

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 201803 Type: WELL API Number: 001-07207 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: no MIT on record

Corrective Action: Comply with 326 Date: 01/04/2021

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 1/4/21 at approximately 1300 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Champlin 78 Amoco B 1 Company Name- Renegade oil and gas API- 05-001-07207 In Adams County Colorado. While there, I observed producing well During this inspection the following possible compliance issues were observed: Weeds uncontrolled on location see pic 1,3,4,5,6,7 Comply with 603 f 1/14/21 stained soil around pump jack see pic 3,4,5,6,7 "Properly treat or dispose of oily waste in accordance with 907.e2/4/21 no BMP under chemical tanks see pic 4,5,6,7 Install adequate BMB for storage of materials that could result in the discharges causing pollution of surface waters per rule 1002 f (2)B 1/14/21 Well has been shut in since 6/1/2018 and needs a mechanical integrity test to ensure wellbore integrity. Contact COGCC engineering No current MIT on record or delinquent as required by Rule 326 1/4/21 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. At time of inspection weather conditions were sunny, cold, recent snow. This is a summary of inspection report.</p>	medinaj	01/04/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699502108	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5321336