

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/22/2020

Submitted Date:

12/29/2020

Document Number:

700404694**FIELD INSPECTION FORM**Loc ID 315379 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10654Name of Operator: LASSO OIL & GAS LLCAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Freeman, Kris	254-727-0435	kfreeman@31operating.com	
Ikenouye, Teri		teri.ikenouye@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230739	WELL	PR	11/08/2000	GW	103-08408	CONTINENTAL 4-28	PR

**General Comment:**

A routine inspection identified the following compliance issues:

- 1) Report past due monthly operations on Form 7. Complete by 7-15-2020.
- 2) Provide bradenhead access. Photo 2. Complete by 2-1-2021.
- 3) Calibrate gas meter. Photo 5. Complete by 2-1-2021.
- 4) Have an emergency phone number that can be reached at all times. Complete by 1-1-2021.

This is a summary of inspection report 700404694.

### Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency phone, 800-209-9762, was called on 12-22-2020 @ 18:12. No one answered and no message service was available.

Corrective Action: Have an emergency phone number that can be reached at all times.

Date: 01/01/2021

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	<span style="color: blue;">Most recent meter calibration in June 2019.</span>		
Corrective Action:	<span style="color: red;">Meters need calibrated annually.</span>	Date:	02/01/2021
Type: Bradenhead	# 1		
Comment:	<span style="color: blue;">Bradenhead access is not present.</span>		
Corrective Action:	<span style="color: red;">Provide bradenhead access with appropriate fittings to allow determination of pressure and fluid flow.</span>	Date:	02/01/2021
Type: Deadman # & Marked	# 4		

Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLs	PBV FIBERGLASS		,	
Comment:	Unable to safely inspect tank level due to snow cover.					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	No berm present. Tank top below adjacent terrain.				
Corrective Action:					Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 230739 Type: WELL API Number: 103-08408 Status: PR Insp. Status: PR**Producing Well**

Comment: Last reported monthly operations were for May 2020. Report past due monthly operations. Last recorded production May 2020.

No audible gas flow at well or meter building. Values from well head tubing to meter building appeared to be open. Tubing gage broke. No casing gage present.

Corrective Action: Submit required Form 7(s) to COGCC.

Date: 07/15/2020

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other						

Comment: [Snow on ground.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Optical Gas Imaging Survey**Survey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Wind: Steady Speed: \_\_\_\_\_ (mph) Direction From: \_\_\_\_\_ Weather: \_\_\_\_\_ Temperature: (F)

Assisting Staff: \_\_\_\_\_ Camera #: \_\_\_\_\_

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
10:05	AM	10:10	AM	Wellhead(s)

Comment: FLIR images acquired of well. No gas leaks detected.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402562805	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5318219">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5318219</a>
700404695	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5318205">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5318205</a>