

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/28/2020

Submitted Date:

12/29/2020

Document Number:

700702074

FIELD INSPECTION FORM

Loc ID 336391 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 200502
Name of Operator: 31 OPERATING
Address: 3021 RIDGE RD #156
City: ROCKWALL State: TX Zip: 75032

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
operating, 31		kfreeman@31operating.com	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231796	WELL	SI	07/01/2017	GW	103-09467	FEE M-31-2-96N	SI
270739	WELL	SI	05/01/2020	GW	103-10406	ANT HILL UNIT RBCWG 6-11D	SI

General Comment:

COGCC Inspection Report Summary

On 12/22/20, I, Inspector Scott Ramsey, conducted a Safety and compliance inspection at 31 Operating 6-11D/31-2, at Location # 336391 in Rio Blanco county Colorado.

This is a limited inspection for Safety and Compliance.

While there, I observed that location has not been visited in quite some time, nor had the access roads been plowed.

During this inspection the following possible compliance issues were observed:

- Debris throughout location (dead weeds)

Refer to photograph of observed compliance issue.

I spoke with Leven who has worked for 31 operations at the lay down yard. He stated that the compressors were pulled out of his field back in October and that he and other pumpers on his side of the field went through and shut all of the wells in November. He had also given me a map of the field and pointed out that he was not sure of some locations that had supply gas running to the burners had been shut off. He also stated that they did NOT evacuate any of the flow lines of fluid. He did not go out to the field with me, he suggested that I could shut the supply gas off if I came across any that needed it. He also stated that all of their phone numbers had been disconnected. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:

Type	Access		
comment:	Snow covered/not plowed		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:

Comment:	<input style="width: 50%;" type="text"/>	Date:	
Corrective Action:	<input style="width: 50%;" type="text"/>	Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	• Debris throughout location (dead weeds)		
Corrective Action:	Remove all debris	Date:	02/01/2021

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:					
Type: Gas Meter Run	# 2				
Comment:					
Corrective Action:					
Type: Other	# 1				
Comment:		well head			
Corrective Action:					
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:					
Type: Bird Protectors	# 2				
Comment:					
Corrective Action:					

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLs	STEEL AST			
Comment:	<input style="width: 90%;" type="text"/>					

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 231796 Type: WELL API Number: 103-09467 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is shut in at time of inspection

Corrective Action: _____ Date: _____

Facility ID: 270739 Type: WELL API Number: 103-10406 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is shut in at time of inspection

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402562456	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5317920
700702109	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5317870