

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/05/2021

Submitted Date:

01/05/2021

Document Number:

699303183**FIELD INSPECTION FORM**Loc ID 318195 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email            | Comment                         |
|--------------|-------|------------------|---------------------------------|
| ,            |       | rwatzman@kpk.com | <a href="#">All Inspections</a> |
| ,            |       | cogcc@kpk.com    | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 240853      | WELL | SI     | 06/01/2020  | OW         | 123-08641 | GRANT 2       | SI          |

**General Comment:**

**Location**Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             | Adequate |       |  |
| Corrective Action:   |          | Date: |  |

|                           |  |  |             |
|---------------------------|--|--|-------------|
| Emergency Contact Number: |  |  |             |
| Comment:                  |  |  |             |
| Corrective Action:        |  |  | Date: _____ |

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| <b>Fencing/:</b>   |                      |       |  |
| Type               | LOCATION             |       |  |
| Comment:           | wooden privacy fence |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | PUMP JACK            |       |  |
| Comment:           | hog fence            |       |  |
| Corrective Action: |                      | Date: |  |

|                           |   |       |                 |
|---------------------------|---|-------|-----------------|
| <b>Equipment:</b>         |   |       | corrective date |
| Type: Prime Mover         | # 1                                       |       |                 |
| Comment:                  | electric motor                            |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Ancillary equipment | # 1                                       |       |                 |
| Comment:                  | electric panel, meterbox and transformers |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Bradenhead          | # 1                                       |       |                 |
| Comment:                  | appears to be plumbed to surface          |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Pump Jack           | # 1                                       |       |                 |
| Comment:                  |   |       |                 |
| Corrective Action:        |   | Date: |                 |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|--|--|--|--|

**Inspected Facilities**Facility ID: 240853 Type: WELL API Number: 123-08641 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI since 6-1-2020

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_

Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_

Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: bradenhead test is past 1 year and needs to be performed annually and well is to be monitored monthly, submit bradenhead test information to COGCC engineering.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Tuesday 1/5/2021 at approximately 1100 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: right;">Grant 2 at API #05-123-08641 in Weld County Colorado.</p> <p>While there, I observed wellsite. SI at time of inspection, SI since 6-1-2020. Tank battery was not inspected at this time only the well.</p> <p>During this inspection no compliance issues were observed:</p> <p>See attached photos.</p> <p>Location: dry, Weather: clear.</p> <p>No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | revasr | 01/05/2021 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description   | URL   |
|--------------|---------------|---|
| 699303184    | location pics | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5322022">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5322022</a> |