

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/05/2021

Submitted Date:

01/05/2021

Document Number:

700702144

**FIELD INSPECTION FORM**

Loc ID 335281 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10531  
Name of Operator: GRIZZLY OPERATING LLC  
Address: 5847 SAN FELIPE #3000  
City: HOUSTON State: TX Zip: 77057

**Findings:**

- 20 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211391	WELL	PR	08/08/2000	GW	045-07151	GIBSON GULCH UNIT 1-30	PR
263754	WELL	PR	03/01/2011	GW	045-08137	GIBSON GULCH UNIT 2-30	PR
284608	WELL	PR	05/10/2007	GW	045-12218	GGU DALEY 41B-30-691	PR
284609	WELL	PR	05/12/2007	GW	045-12217	GGU DALEY 44A-19-691	PR
300468	WELL	PR	02/16/2010	GW	045-17905	GGU DALEY 11A-29-691	PR
300469	WELL	PR	02/16/2010	GW	045-17906	GGU DALEY 12C-29-691	PR
300470	WELL	PR	02/16/2010	GW	045-17907	GGU DALEY 11D-29-691	PR
300471	WELL	PR	02/16/2010	GW	045-17908	GGU DALEY 41A-30-691	PR
300472	WELL	PR	02/16/2010	GW	045-17909	GGU DALEY 44B-19-691	PR
300473	WELL	PR	02/16/2010	GW	045-17910	GGU DALEY 41C-30-691	PR

**General Comment:**

[COGCC Inspection Report Summary](#)  
On Tuesday 1/5/2021 at approximately 1130, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly GGU 1-30, at Location # 335281 in Garfield county Colorado.  
While there, I observed normal production operations. All meters have been calibrated on location within the past year. Three (3) Braden heads are tied into sales.  
During this inspection the following possible compliance issues were observed:

- No evidence of tracking control BMP's
- One (1) tank label is falling off

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	snow covered/plowed		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	• One (1) tank label is falling off		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	_____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 10		
Comment:	Three (3) Braden heads are tied into sales.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	chemical tanks at well heads		
Corrective Action:		Date:	
Type: Gas Meter Run	# 10		
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	OTHER	HEATED STEEL AST		,
Comment:	375 BBL tanks and Three (3) tanks are NOT heated				
Corrective Action:					Date:

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211391	Type:	WELL	API Number:	045-07151	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	263754	Type:	WELL	API Number:	045-08137	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	284608	Type:	WELL	API Number:	045-12218	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	284609	Type:	WELL	API Number:	045-12217	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300468	Type:	WELL	API Number:	045-17905	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300469	Type:	WELL	API Number:	045-17906	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300470	Type:	WELL	API Number:	045-17907	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300471	Type:	WELL	API Number:	045-17908	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				

Facility ID: 300472 Type: WELL API Number: 045-17909 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 300473 Type: WELL API Number: 045-17910 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited storm water inspection due to snow cover  
 • No evidence of tracking control BMP's

Corrective Action: Provide proof of tracking control BMP's

Date: 02/05/2021

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702149	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5322280">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5322280</a>