

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/06/2021

Submitted Date:

01/06/2021

Document Number:

701100970

**FIELD INSPECTION FORM**Loc ID 334705 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name          | Phone        | Email                              | Comment |
|-----------------------|--------------|------------------------------------|---------|
| Inspection, Terra TEP | 970-285-9377 | COGCCInspectionReports@terraep.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name         | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 285036      | WELL | PR     | 06/08/2006  | GW         | 045-12351 | DIAMOND ELK SR 311-7  | PR          |
| 285580      | WELL | PR     | 10/24/2006  | GW         | 045-12520 | DIAMOND ELK RWF 414-6 | PR          |

**General Comment:****COGCC Inspection Report Summary**

I, Inspector Mike Longworth, conducted an inspection at TEP ROCKY MOUNTAIN LLC, DIAMOND ELK-67S95W 1SESE, Location ID: 334705 in Garfield County, Colorado.

During this inspection the following possible compliance issues were observed:

Dead weed debris on location.

Battery sign is weathered.

**Location**

|                    |                         |       |  |
|--------------------|-------------------------|-------|--|
| <b>Lease Road:</b> |                         |       |  |
| Type               | Access                  |       |  |
| comment:           | Snow packed access road |       |  |
| Corrective Action  |                         | Date: |  |

Overall Good: ☒

|                      |   |       |            |
|----------------------|---|-------|------------|
| <b>Signs/Marker:</b> |   |       |            |
| Type                 | WELLHEAD                                |       |            |
| Comment:             |   |       |            |
| Corrective Action:   |   | Date: |            |
| Type                 | BATTERY                                 |       |            |
| Comment:             | Battery sign is weathered.              |       |            |
| Corrective Action:   | Install sign to comply with Rule 210.e. | Date: | 04/07/2021 |
| Type                 | TANK LABELS/PLACARDS                    |       |            |
| Comment:             |   |       |            |
| Corrective Action:   |   | Date: |            |

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |                               |       |            |
|--------------------|-------------------------------|-------|------------|
| Type               | DEBRIS                        |       |            |
| Comment:           | Dead weed debris on location. |       |            |
| Corrective Action: | Comply with Rule 603.f .      | Date: | 01/15/2021 |

Overall Good: ☐

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | WELLHEAD     |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | SEPARATOR    |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |

|                                   |  |       |                 |
|-----------------------------------|--|-------|-----------------|
| <b>Equipment:</b>                 |  |       | corrective date |
| Type: Bradenhead                  | # 2                                    |       |                 |
| Comment:                          | Braden head accessible for monitoring. |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Plunger Lift                | # 2                                    |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Bird Protectors             | # 2                                    |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Horizontal Heated Separator | # 2                                    |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |

**Tanks and Berms:**

| Contents           | # | Capacity  | Type      | Tank ID | SE GPS |
|--------------------|---|-----------|-----------|---------|--------|
| PRODUCED WATER     | 1 | <100 BBLs | STEEL AST |         | ,      |
| Comment:           |   |           |           |         |        |
| Corrective Action: |   |           |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 80 bbl   |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**Facility ID: 285036 Type: WELL API Number: 045-12351 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 285580 Type: WELL API Number: 045-12520 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Culverts                | Pass                  |               |                          |         |
| Ditches          |                 |                         |                       |               |                          |         |
|                  |                 | Ditches                 | Pass                  |               |                          |         |
| Compaction       |                 |                         |                       |               |                          |         |

Comment: [Limited BMPs inspection due to snow cover.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                    | URL   |
|--------------|--------------------------------|---|
| 701100971    | Inspection 701100970 photo log | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5323656">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5323656</a> |