

Inspection Photos

API: 071-08734

Operator: OGRIS OPERATING LLC

Inspection Date: 1/6/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08734 | Date: 1/6/2021

Inspection Photos



Photo 1. Facing south along the main road ascending the hill side. The road has been regraded. Red arrow points to dirt row which will prevent stormwater flow toward the culvert. Better diversion is needed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08734 | Date: 1/6/2021

Inspection Photos



Photo 2. Facing northwest along the road ascending the hill side.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08734 | Date: 1/6/2021

Inspection Photos



Photo 3. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08734 | Date: 1/6/2021

Inspection Photos



Photo 4. Water is leaking from the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08734 | Date: 1/6/2021