



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Sheridan 11-2

API: 05-103-11920

Inspection: 700404864



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

Sheridan 11-2

API: 05-103-11920

Inspection: 700404864



40.06599, -107.90795, 6386.1ft, 328°
01/06/2021 11:34:41 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Plugged well.

Sheridan 11-2

API: 05-103-11920

Inspection: 700404864



40.06613, -107.90815, 6553.1ft, 33°
01/06/2021 11:33:52 AM



40.06586, -107.90762, 6393.4ft, 43°
01/06/2021 11:26:48 AM





40.06576, -107.90818, 6383.8ft, 63°
01/06/2021 11:35:33 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 7. Tanks.

Sheridan 11-2

API: 05-103-11920

Inspection: 700404864



40.06622, -107.90849, 6366.1ft, 278°
01/06/2021 11:30:42 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 8. Pipe or cable reels.

Sheridan 11-2

API: 05-103-11920

Inspection: 700404864



40.06636, -107.90848, 6391.7ft, 21°
01/06/2021 11:31:09 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 9. Tubing.

Sheridan 11-2

API: 05-103-11920

Inspection: 700404864



40.06635, -107.90852, 6390.6ft, 303°
01/06/2021 11:31:22 AM