

Inspection Photos

API: 071-07680

Operator: OGRIS OPERATING LLC

Inspection Date: 1/6/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest toward the access road. The erosion along the road has been repaired. Additional stabilization should be performed to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07680 | Date: 1/6/2021

Inspection Photos



Photo 2. The culvert along the access road has been cleaned out and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07680 | Date: 1/6/2021

Inspection Photos



Photo 3. The erosion off the fill slope of the road has been filled in. This area will need to be seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07680 | Date: 1/6/2021

Inspection Photos



Photo 4. Facing northeast toward the access road. Stormwater The culvert has been cleaned out and diversion toward the culvert repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07680 | Date: 1/6/2021

Inspection Photos



Photo 5. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07680 | Date: 1/6/2021