

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

11/11/2020

Document Number:

402467324

## Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and

### Operator Information

OGCC Operator Number: 46290 Contact Person: Mani Silva  
Company Name: KP KAUFFMAN COMPANY INC Phone: (303) 8254822  
Address: 1675 BROADWAY, STE 2800 Email: regulatory@kpk.com  
City: DENVER State: CO Zip: 80202  
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes ☒ No ☐

### OFF LOCATION FLOWLINE

#### FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 318360 Location Type: Manifold  
Name: DITLEV-SIMONSEN GAS UNIT-62N67W Number: 31NWSW  
County: WELD  
Qtr Qtr: NWSW Section: 31 Township: 2N Range: 67W Meridian: 6  
Latitude: 40.091980 Longitude: -104.938600

#### Description of Corrosion Protection

Fiberglass pipelines are resistant to most acids, bases, oxidizing agents, metal salts, reducing gases and sulfur gases. These pipelines have been utilized by KPK because of their corrosion resistance. As such, additional corrosion protection is not needed for these pipelines.

#### Description of Integrity Management Program

Production and upkeep of KPK's assets involves regular hands-on operation by KPK's field crews. These field crews not only maintain safe production, but also conduct routine inspections to confirm proper integrity of the production systems. While pipeline integrity issues are minimal due to pipeline materials and low operating pressure, KPK regularly inspects and pressure tests all lines to ensure pipeline integrity is maintained.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

Construction of pipelines is generally not occurring. When necessary to remedy a pipeline issue, KPK typically assesses all conditions to determine the proper construction method. A combination of boring and open trench are utilized by KPK.

#### FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 475237 Flowline Type: Wellhead Line Action Type:

#### OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Manifold

**Flowline Start Point Location Identification**

Location ID: 318405 Location Type: \_\_\_\_\_ Well Site ☐  
Name: DITLEV-SIMONSEN C-62N67W Number: 31SESW  
County: WELD No Location ID  
Qtr Qtr: SESW Section: 31 Township: 2N Range: 67W Meridian: 6  
Latitude: 40.089920 Longitude: -104.935990  
Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Fiberglass Max Outer Diameter:(Inches) 3.000  
Bedding Material: Native Materials Date Construction Completed: 12/13/1976  
Maximum Anticipated Operating Pressure (PSI): 40 Testing PSI: 40  
Test Date: 08/18/2020

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: \_\_\_\_\_

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 475235 Flowline Type: Wellhead Line Action Type: \_\_\_\_\_

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Manifold

**Flowline Start Point Location Identification**

Location ID: 318385 Location Type: \_\_\_\_\_ Well Site ☐  
Name: DITLEV-SIMONSEN C-62N67W Number: 31NWSW  
County: WELD No Location ID  
Qtr Qtr: NWSW Section: 31 Township: 2N Range: 67W Meridian: 6  
Latitude: 40.093100 Longitude: -104.939800  
Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Fiberglass Max Outer Diameter:(Inches) 3.000  
Bedding Material: Native Materials Date Construction Completed: 10/24/1976  
Maximum Anticipated Operating Pressure (PSI): 40 Testing PSI: 40  
Test Date: 08/18/2020

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: \_\_\_\_\_

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 475234 Flowline Type: Wellhead Line Action Type: \_\_\_\_\_

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Manifold

**Flowline Start Point Location Identification**

Location ID: 318207 Location Type: \_\_\_\_\_ Well Site ☐  
Name: DITLEV-SIMONSEN C-62N67W Number: 31NESW  
County: WELD No Location ID  
Qtr Qtr: NESW Section: 31 Township: 2N Range: 67W Meridian: 6  
Latitude: 40.093240 Longitude: -104.935940

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Fiberglass Max Outer Diameter:(Inches) 3.000  
Bedding Material: Native Materials Date Construction Completed: 04/27/1976  
Maximum Anticipated Operating Pressure (PSI): 40 Testing PSI: 40  
Test Date: 08/18/2020

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: \_\_\_\_\_

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 475236 Flowline Type: Wellhead Line Action Type: \_\_\_\_\_

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Manifold

**Flowline Start Point Location Identification**

Location ID: 318206 Location Type: \_\_\_\_\_ Well Site ☐  
Name: DITLEV-SIMONSEN B-62N67W Number: 31SWSW  
County: WELD No Location ID  
Qtr Qtr: SWSW Section: 31 Township: 2N Range: 67W Meridian: 6  
Latitude: 40.089960 Longitude: -104.939400

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Fiberglass Max Outer Diameter:(Inches) 3.000  
Bedding Material: Native Materials Date Construction Completed: 05/12/1976  
Maximum Anticipated Operating Pressure (PSI): 40 Testing PSI: 40  
Test Date: 08/18/2020

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: \_\_\_\_\_

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:****OPERATOR COMMENTS AND SUBMITTAL**

Comments

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: \_\_\_\_\_ Date: 11/11/2020 Email: regulatory@kpk.com

Print Name: Jeremy Kauffman Title: Analyst

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved:  Director of COGCC Date: 1/7/2021

## Conditions of Approval

**COA Type**

**Description**

## Attachment Check List

**Att Doc Num**

**Name**

402467324	Form44 Submitted
402530773	PRESSURE TEST
402530774	PRESSURE TEST

Total Attach: 3 Files

## General Comments

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)

