

Inspection Photos

1/04/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 475753

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 475753



Photo 1: Photo taken from the southeast corner of the Pad, facing west. Photo 1-3 provide an overview of the Location from west, northwest to north.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 475753



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 475753



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 475753



Photo 4: Photo taken from the south end of the Location, facing south. Photo shows topsoil stockpile. Hydromulch observed on soils not covered with snow.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 475753



Photo 5: Photo taken from the cuts lope on the west end of the Location, facing west. Photo shows areas where erosion degradation previously documented; Due to snow cover, inspector was unable to accurately assess if BMPs have been installed in accordance with good engineering practices, are sufficient for the sites conditions and maintained in proper functioning condition. A followup inspection will need to be conducted.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 475753



Photo 6: Photo taken from the west end of the Location, facing north. See comments under photo 5.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 475753



Photo 7: Photo taken from the south end of the Location, facing north. Photo shows tank on Location missing signage and labeling. Signage due within 60 days of installation per Rule 210.b.(2). Labeling required on tanks per 210.d.(1).



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 475753



Photo 8: Photo taken from the Location, facing west. Photo shows wells; All permitted wells on the Location have been drilled; wells on Location missing signage. Signage due within 60 days of completion per Rule 210.b.(2)



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 475753



Photo 9: Continued from photo 8. Photo shows equipment observed on Location.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 475753



Photo 10: Photo taken from the northeast end of the Location, facing west. Photo shows cut slopes of Location; Hydromulch observed on slopes. Due to snow cover, it is unclear if additional BMPs, such as run-on controls, have been installed in conjunction with the hydromulch.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 475753



Photo 11: Photo taken from the north end of the Location, facing northeast. Photo shows "Slash Stockpile" and sign.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 475753



Photo 12: Photo of tanks on the northeast end of the Location. Signs on tanks state "Produced Water".



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 475753



Photo 13: Photo taken from the access road at the stream crossing, facing west. Photo shows proper BMPs per good engineering practices remain missing, or insufficient to stabilize access road at stream crossing



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 475753



Photo 14: Continued from photo 13. Photo shows Operator installed hydromulch on slopes along areas cut during construction of the access road.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 475753



Photo 15: See comments under photo 15. Photo also shows the streambed has been used as a turn-around area.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 475753



Photo 16: Photo taken from the access road at the stream crossing, facing west. Photo shows proper BMPs per good engineering practices remain missing to protect the waterway and stabilize access road at stream crossing



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 475753



Photo 17: See comments under photo 16.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 475753



Photo 18: See comments under photo 16.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 475753



Photo 19: See comments under photo 16.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 475753



Photo 20: See comments under photo 16. It was also observed that the streambed has been used as a turn-around area



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources