

Inspection Photos  
Operator: Epic Energy  
API: 067-08220  
Date: 1/6/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with grasses such as western wheatgrass, smooth brome, and crested wheatgrass.





Photo 3. View of the eastern project area from the southeastern corner facing northward. Fill slopes are bermed and revegetating.



Photo 4. View of debris within the southern project area.





Photo 5. View of reference area comprised of pinyon and juniper woodland with sagebrush, squirreltail, and narrow leaf penstemon.