

Inspection Photos
Operator: Simcoe
API: 067-07956
Date: 1/6/2021



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Location is largely snow covered. Erosional channels appear to be forming in the fill slope.



Photo 3. View of erosional channel in the eastern project area.



Photo 4. View of the southern project area from the southeastern corner facing westward.



Photo 5. View of reference area comprised of pinyon and juniper woodland with sagebrush, squirreltail, and narrow leaf penstemon.