

Inspection Photos

Operator: WPX

API: 067-07066

Date: 1/6/2021



Photo 1. View of the project area from the southwestern corner facing center. Location is not recontoured.



Photo 2. View of the western cut slope facing northward. Evidence of erosional channeling and bare soils observed. Cut slope was not recontoured.



Photo 3. Another view of bare soils and steep cut-slopes lacking recontouring.



Photo 4. View of location from the northeastern corner facing center. Large flat location remains.



Photo 5. View of reference area comprised of pinyon and juniper woodland with sagebrush, squirreltail, and narrow leaf penstemon.