

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/04/2021

Submitted Date:

01/08/2021

Document Number:

688309382**FIELD INSPECTION FORM**Loc ID 317054 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10690Name of Operator: IMPETRO RESOURCES LLCAddress: 2820 LOGAN DRIVECity: LOVELAND State: CO Zip: 80538**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Bradley, Sam	970-593-8626	sbradley.impetro@gmail.com	Principal Agent
Gibson, Rick	970-768-6880	rtgibson01@msn.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
235298	WELL	PR	03/01/2020	OW	121-07510	LIPPELMANN 2	PR

General Comment:

Pit Inspection, no oil on pit (no photos taken)

Inspected Facilities									
Facility ID:	235298	Type:	WELL	API Number:	121-07510	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID: _____

Lat: _____

Long: _____

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type: _____

Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:Fencing Type: None

Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____

Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____

Oil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____