

Inspection Photos

API# 045-06745

Operator: Chevron

Insp #:692402874

Insp Date: 12/28/2020





Photo#1:
There is No Evidence of the DA Well on this Active Location.

December 28, 2020



Photo#2:
Google Earth; Aerial view of corrected Well position.

December 28, 2020