

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/05/2021

Submitted Date:

01/05/2021

Document Number:

700702144

FIELD INSPECTION FORM

Loc ID 335281 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 10531
 Name of Operator: GRIZZLY OPERATING LLC
 Address: 5847 SAN FELIPE #3000
 City: HOUSTON State: TX Zip: 77057

Findings:
20 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211391	WELL	PR	08/08/2000	GW	045-07151	GIBSON GULCH UNIT 1-30	PR
263754	WELL	PR	03/01/2011	GW	045-08137	GIBSON GULCH UNIT 2-30	PR
284608	WELL	PR	05/10/2007	GW	045-12218	GGU DALEY 41B-30-691	PR
284609	WELL	PR	05/12/2007	GW	045-12217	GGU DALEY 44A-19-691	PR
300468	WELL	PR	02/16/2010	GW	045-17905	GGU DALEY 11A-29-691	PR
300469	WELL	PR	02/16/2010	GW	045-17906	GGU DALEY 12C-29-691	PR
300470	WELL	PR	02/16/2010	GW	045-17907	GGU DALEY 11D-29-691	PR
300471	WELL	PR	02/16/2010	GW	045-17908	GGU DALEY 41A-30-691	PR
300472	WELL	PR	02/16/2010	GW	045-17909	GGU DALEY 44B-19-691	PR
300473	WELL	PR	02/16/2010	GW	045-17910	GGU DALEY 41C-30-691	PR

General Comment:

COGCC Inspection Report Summary
 On Tuesday 1/5/2021 at approximately 1130, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly GGU 1-30, at Location # 335281 in Garfield county Colorado.
 While there, I observed normal production operations. All meters have been calibrated on location within the past year. Three (3) Braden heads are tied into sales.
 During this inspection the following possible compliance issues were observed:

- No evidence of tracking control BMP's
- One (1) tank label is falling off

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:	snow covered/plowed		
Corrective Action	L		Date:

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	• One (1) tank label is falling off		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:			Date:

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	chemical tanks at well heads		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 10		
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:			Date:
Type: Bradenhead	# 10		
Comment:	Three (3) Braden heads are tied into sales.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	OTHER	HEATED STEEL AST		,
Comment:	375 BBL tanks and Three (3) tanks are NOT heated				
Corrective Action:					Date:

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211391	Type:	WELL	API Number:	045-07151	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	263754	Type:	WELL	API Number:	045-08137	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	284608	Type:	WELL	API Number:	045-12218	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	284609	Type:	WELL	API Number:	045-12217	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300468	Type:	WELL	API Number:	045-17905	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300469	Type:	WELL	API Number:	045-17906	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300470	Type:	WELL	API Number:	045-17907	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300471	Type:	WELL	API Number:	045-17908	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

Facility ID: <u>300472</u>	Type: <u>WELL</u>	API Number: <u>045-17909</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Producing Well

Comment: <u>producing</u>	
Corrective Action:	Date:

Facility ID: <u>300473</u>	Type: <u>WELL</u>	API Number: <u>045-17910</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Producing Well

Comment: <u>producing</u>	
Corrective Action:	Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited storm water inspection due to snow cover
• No evidence of tracking control BMP's

Corrective Action: Provide proof of tracking control BMP's

Date: 02/05/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402566773	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5322302
700702149	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5322280